



Network Disclosure Announcement No. 769

Short Term Public Notice Under Rule 51.333(a)

CenturyLink's Internet address: <http://qwest.centurylink.com/disclosures/>

Copper Retirements in Arizona, Colorado, Iowa, North Dakota, Oregon, and South Dakota

First Implementation Date: *December 31, 2012*

Original Date Posted:

August 15th, 2012

Summary:

Copper Retirements are necessary to respond to various factors in the Outside Plant, including road construction, maintenance problems, and growth accommodation. Replacement cables may be either copper or fiber. Specific information will be provided with each disclosure.

**Locations, Timing of
Deployments & Interface
Requirements:**

The following gives additional details on the copper retirement(s):

This update is needed to reflect a correction to the Wire Center CLLI for Grand Forks, ND.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	FDI Address(es)	Replacing
AZ	Phoenix South PHNXAZSO	01-20-2013	311321	E.365915	8409 S 16 th St.	Abandonment of approximately 1855 ft of defective copper cable requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). All existing services will continue to be supported; however, after the cut to DLC, new copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	FDI Address(es)	Replacing
CO	Steamboat Springs STSPCOMA	05-12-2013	420331	E.347631	30019 W US Hwy 40	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). All existing services will continue to be supported; however, after the cut to DLC, new copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
CO	Arvada ARVDCOMA	02-15-2013	411231	E.299310	5290 Miller St	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). All existing services will continue to be supported; however, after the cut to DLC, new copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
IA	Des Moines East DESMIAEA	12-31-2012	336503	E.340796	481 S Hickory Blvd	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). All existing services will continue to be supported; however, after the cut to DLC, new copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	FDI Address(es)	Replacing
ND	Grand Forks GDFRNDCO GDFRNDBC	12-31-2013	350404	E.340737	1028 Columbia Rd S	Road construction forces CenturyLink to abandon its copper cables and transfer working services to a fiber fed digital loop carrier system (DLC). All existing services will continue to be supported; however, after the cut to DLC, new copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
OR	Keizer SALMOR59	03-31-2013	225831/225832	E.340611	3990 Ward Dr NE 4000 Ward Dr NE	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). All existing services will continue to be supported; however, after the cut to DLC, new copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
SD	Aberdeen ABRDSDCO	03-31-2013	220202/220302	E.372434	204 N Arch St 802NE3	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). All existing services will continue to be supported; however, after the cut to DLC, new copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	FDI Address(es)	Replacing
SD	Rapid City RPCYSDCO	02-12-2013	692302	E.378129	X 618	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). All existing services will continue to be supported; however, after the cut to DLC, new copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

Additional Information:

Any customer premises equipment vendor/manufacturer or enhanced services provider desiring additional technical information in conjunction with this Disclosure can contact:

Abdennaceur Boudhaouia
303-707-8561
Jamal.Boudhaouia@CenturyLink.com